


B6-1

Box List



Item No: B6-1			Worker	Q C	ganger
Box		Quantity			
Part name		Quantity			
A	Front wire	1pc			
B	Back wire	1pc			
C	Left wire	1pc			
D	Right wire	1pc			
E	Upper perch	1pc			
F	Bottom perch	1pc			
G	Front & back legs	2pcs			
H	Left & right legs	2pcs			
I	Grill	1pc			
J	Bottom grill	1pc			
K	Upper top wire	2pcs			
L	Low top wire	2pcs			
M	Plastic bottom	1pc			
N	Wheels	4pcs			
O	Feeders	3pcs			
P	Holder	3pcs			
Q	Screw bag	1pc			
R	Screw single (M4x20)	20pcs			
S	Screw single (M5x35)	8pcs			
T	Screw single (M6x10)	6pcs			

1. Screw part G with part H to form a stand;
2. Attach part N onto bottom of part H;
3. Insert part J onto bottom of the stand;
4. Put part M on the stand;
5. Screw part A, part B, part C, part D to form the top cage body;
6. Attach part L with part C and part D, then screw it with part A and part B;
7. Screw part K with part A and part B;
8. Slide part I in place underneath the cage body;
9. Screw part P with feeder door, then put part O into part P;
10. Insert part E and part F into the cage body;
11. Put the top cage body into the slot of part M.
Then assembly finished.

Made in China